

# Oil Field Environmental Incident Summary

**Incident:** 20150205171745

**Date/Time of Notice:** 02/05/2015 17:17

**Responsible Party:** XTO ENERGY INC.

**Well Operator:** XTO ENERGY INC.

**Well Name:** ROXY 21X-6B

**Field Name:** WEST CAPA

**Well File #:** 22681

**Date Incident:** 2/5/2015

**Time Incident:** 07:10

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 96

**Sec:** 6

**Qtr:**

**Location Description:**

**Submitted By:** Kaylan Dirkx

**Received By:**

**Contact Person:** Kaylan Dirkx

P.O Box 1589

Sidney, MT 59270

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Barrels	4	Barrels	4	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/19/2015

**Clean Up Concluded:** 2/12/2015

**Risk Evaluation:**

None, personnel was on site and shut in the well.

**Areal Extent:**

**Potential Environmental Impacts:**

None, spill was contained on location and the wellhead was shut-in immediately.

**Action Taken or Planned:**

Damaged bull plug was replaced and all other plugs on the wellhead were inspected.

**Wastes Disposal Location:** Liquids recovered will be returned to production tanks, Impacted soils will be disposed at R360.

**Agencies Involved:**

**Updates**

---

**Date:** 2/6/2015      **Status:** Reviewed - Assigned to Other Agency

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to other causes, remained on location according to the report. NDIC retains oversight.